

Polaroid ID Card Printer Firmware Upgrade

Go Green and Save! Enable more eco-friendly and economical operation of your Polaroid printer.

Perform this important and FREE firmware upgrade today for Polaroid P3000, P3000E, P4000, P4000E, and P5000E printers.

Go to www.screencheckeu.com and click on the link Polaroid ID Card Printer Firmware Upgrade.

Firmware 33.xx.x or higher is required when using the second generation ribbons on Polaroid P3000E/P4000E/P5000E printers. New type print ribbons can be recognized by the '1' in the article code e.g. RIB-POL-1-5P200.

Old type ribbons are not compatible with the new P3500S and P5500S card printers.

FREE POLAROID PRINTER FIRMWARE UPGRADE



new eco ribbons to be used in combination with firmware 33.XX.X

Please feel free to contact our support department in case of questions (support@screencheck.com)

**SCREEN
CHECK**

 Polaroid.